

# Phoenix Gold Flat Rate Repair Charges

2005-2006

MS SERIES	RATE	ZXSERIES	RATE	XENON SERIES
*FRANK-AMP-N-STIEN	\$175.00	*OCTANE/REACTOR	\$240.00	X100.2 USA /RX100.2 USA
*MQ 430	\$115.00	*ZX200 & 250	\$110.00	X100.4 USA/RX100.4 USA
*MS1000	\$175.00	*ZX350,450 & 500	\$130.00	X1200.1 USA/RX1200.1 USA
*MS2125	\$140.00	*ZX400TI & ZX600TI	\$110.00	X200.2 USA/RX200.2 USA
*MS2250	\$175.00	*ZX475TI/TI500.4	\$125.00	X200.4 USA/RX200.4 USA
*MS250	\$95.00	*ZX950	\$175.00	X400.1 USA/RX400.1 USA
*MS275	\$100.00	^TI1000.2/TI1200.1	\$140.00	X600.1 USA/RX600.1 USA
^MS1000 TA	\$175.00	^TI400.2 & TI600.2	\$110.00	
^MS2125 TA	\$140.00	^TIPOWERCORE (Capacitor)**	\$275.00	
^MS2250 TA	\$175.00	^TI800.1	\$135.00	
SON OF FRANK	\$175.00	^TI900.7	\$200.00	
MPS SERIES	RATE	ZPA SERIES	RATE	OCTANE "R" SERIES
*MPS2220	\$110.00	*ZPA0.3	\$200.00	R.15.0:1 USA/RR15.0:1 USA
*MPS2240	\$110.00	*ZPA0.5	\$220.00	R2.0:1/RR2.0:1 USA
*MPS2500	\$175.00	ZPX	\$100.00	R2.5:2 USA/RR2.5:2 USA
M SERIES	RATE	SIGNAL PROCESSORS	RATE	R4.0:2 USA/RR4.0:2 USA
*BANDIT	\$110.00	*AX204 & AX406	\$60.00	R5.0:1 USA/RR5.0:1 USA
*M100	\$125.00	*BASSCUBE (T & TI)	\$50.00	R5.0:4 USA/RR5.0:4 USA
*M25	\$105.00	*EQ215 (ALL)	\$70.00	R5.1MT USA/RR5.1MT USA
*M44	\$115.00	*EQ230 AND 232	\$85.00	R8.0:1USA/RR8.0:1 USA
*M50	\$115.00	*MX2	\$50.00	R8.0:4 USA/RR8.0:4 USA
*OUTLAW	\$150.00	*MX3	\$65.00	R9.0:5 USA/RR9.0:5 USA
*ROUTE 66	\$170.00	*PLDI AND 2	\$35.00	
SAPPHIRE SERIES	RATE	*TBA2 XMITTER AND RECEIVER	\$35.00	MISC.
*SA1.0	\$65.00	*TBATI XMITTER AND RECEIVER	\$35.00	CYCLONE
*SA1.4	\$135.00	^TDD5	\$60.00	RMD
*SA1.5	\$135.00	^TI AND T215	\$70.00	LPL44
*SA3.0	\$75.00	^TIDD10	\$60.00	
XS SERIES	RATE	^TIDEQ30 & 232	\$85.00	LINE DRIVERS
*XS2200	\$95.00	^TIDEQCOMP	\$100.00	TLD2
*XS2300	\$95.00	^TLDT	\$35.00	TLD22
*XS2500	\$105.00	^TX204 AND TX406	\$60.00	TLD66
*XS4300	\$110.00			SLD44
*XS4600	\$110.00			
*XS6600	\$135.00			**TIPOWERCORE (Minor Repairs)
TANTRUM SERIES	RATE	QX SERIES	RATE	RSD SERIES
^T1200.1	\$125.00	*QX2100	\$65.00	RSD250.2
^T200.2	\$95.00	*QX2180/QX2350	\$90.00	RSD300.4
^T250.2	\$95.00	*QX4150	\$95.00	RSD500.4
^T300.2	\$110.00	^QX100.2 USA	\$95.00	RSD300.1
^T400.4	\$130.00	^QX150.4 USA	\$125.00	RSD600.1
^T500.2	\$115.00	^QX180.2 USA	\$95.00	RSD1200.1
^T600.4	\$135.00	^QX300.1 USA	\$100.00	
		^QX300.4 USA	\$130.00	
		^QX500.1D USA	\$140.00	
		^QX500.5 USA	\$150.00	
		^QX90.2 USA	\$90.00	
		^QX900.1D USA	\$150.00	
		^QX350.2 USA	\$110.00	

**Phoenix Gold Flat Rate Repair Charges**

2005-2006

RATE
\$95.00
\$130.00
\$135.00
\$95.00
\$125.00
\$100.00
\$100.00

RATE
\$140.00
\$95.00
\$95.00
\$100.00
\$110.00
\$125.00
\$190.00
\$125.00
\$130.00
\$150.00

RATE
\$100.00
\$35.00
\$20.00

RATE
\$35.00
\$35.00
\$35.00
\$35.00

\$65.00
---------

RATE
\$105.00
\$125.00
\$135.00
\$110.00
\$135.00
\$140.00